



**1. Thoroughly clean test area.**

- Pressure-washing is preferred.
- Begin at the lowest point of the test area and pressure-wash toward the highest point of the test area (bottom to top).
- Once at the highest point, rinse with clean water to remove all residue from the test surface (top to bottom).

**2. If you are unable to pressure-wash the area, use a Scotch Brite pad to scrub the surface before rinsing.**

**3. Allow the test area to dry thoroughly.**

**4. Apply approximately 32 wet mils (2 gallons per 100 sq. ft.) of coating onto the clean dry substrate.**

**5. In three separate areas, embed three cloth strips (1 in. wide by 6 in. long) into the wet coating.**

- Allow 2 in. of the fabric to overhang out of the wet coating.
- When the cloth strip placement is finished, apply enough coating to the topside to wet-out the topside of the cloth.
- Brush the coating lightly to ensure no air bubbles are entrapped.
- Leave the 2 in. protruding end of fabric uncoated.

**6. Allow the test areas to cure for 1-2 weeks before checking adhesion.**

- Adhesion and curing time frame depend on climate conditions (temperature, humidity, etc.).
- If an early test fails, wait the full two weeks to ensure coating has enough time to cure for true adhesion results.
- When checking adhesion, pull the fabric strip straight up.
- There must be a minimum two lbs. of “pull strength” for the coating adhesion to be considered acceptable.
  - If little to no effort is needed when pulling the strip, the application likely did not adhere properly.
  - If it is difficult to pull the strip or the fabric is separating from the coating, the adhesion is likely acceptable.

**7. Please consult American WeatherStar Technical Services with all test results.**